



**BEFORE:**  
Although the coating on this bird feeder still looked good, my planting scheme had changed so the bird feeder had to change too! After a good clean down and light sanding it was ready.



**AFTER:**  
The lid was treated with Royal Exterior Anthracite Grey with the main body in Royal Lemon Yellow giving this bird feeder a new, fresh and attractive colour scheme to sit perfectly next to the honeysuckle & roses.



**BEFORE:**  
This garden trug had been used often and was showing signs of wear and tear and old age.

**AFTER:**  
All surfaces were given a good clean with warm water & detergent and allowed to dry fully. The handle was painted with one coat of Royal Exterior Hazelnut and Royal Exterior China Clay was painted on the trug slats to give it a new lease of life and protection.



**BEFORE:** untreated pine planter was cleaned before sprucing up and protecting.

**AFTER:** Two coats of Royal Exterior Lime Green was applied to create a beautiful frame and contrast against the scarlet red cyclamen.



**BEFORE:**  
An old bird nesting box was in desperate need of a makeover. Surfaces were sanded lightly and gaps filled with caulk.



**AFTER:**  
A couple of coats of Royal Exterior Mendip Mist were applied to protect the wood against weather and make it look a lot more attractive, contrasting nicely with the Royal Taupe on the shed.



**BEFORE:**  
Planter treated in Poppy Wood Stain & Protector many years ago.

**AFTER:**  
Old coating was lightly sanded and surfaces cleaned before applying fresh coats of Royal Exterior Anthracite Grey.

