



# Sun Loungers Makeover



LEFT & BELOW:  
A set of untreated hardwood sun loungers was suffering from weathering, UV fade and algae growth.



This once attractive and expensive set of furniture had become an eyesore and was in desperate need of some love and attention.



LEFT:  
The timber was stripped back using an industrial powered pressure washer then the remaining algae killed and removed by painting on a solution of water and bleach.



LEFT & ABOVE:  
Royal Exterior in Hazelnut was applied to leave a superbly rich colour with a natural looking finish that allows grain to shine.



Once dry the timber was ready for a protective wood stain to be applied.

LEFT:  
Some elbow grease and two coats of Royal Exterior was all that was needed to transform this set of sun loungers in to beautiful pieces of furniture that set the scene for partying, picnicing, relaxation and fun.

The hard-wearing, attractive water-repellent coating is set to protect the loungers for many years of enjoyment.